



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
WILLINGTON ROAD	o/s 43	TR: Felling	F/W uplifting and cracking	Platanus x hispanica	Betula ermanii	Plant in existing pit o/s 43-45
WILLINGTON ROAD	opp 43	TR: Felling	Kerbstone displaced, roots likely to be damaged upon reinstatement	Tilia x europea	Betula ermanii	Plant in same position OPPOSITE 43-45 Willington Rd
WILLINGTON ROAD	opp 99, (junction of Willington and Millthorpe Rd)	TR: Felling	Extensive c/w and kerb disruption	Platanus x hispanica	Betula ermanii	Plant in same position, OPPOSITE 99 Willington Rd